



# STATE OF CONNECTICUT

## BOARD OF TRUSTEES FOR THE STATE COLLEGES

P. O. BOX 2008                      NEW BRITAIN, CONNECTICUT 06050  
TEL. NEW BRITAIN: 203-229-1607                      TEL. HARTFORD: 203-566-7373

### RESOLUTION

concerning

### CAPITAL PROJECTS

July 14, 1978

- WHEREAS, The Governor, the General Assembly, the Board of Higher Education, and the Commissioner of Public Works, have supported the Trustees' request for certain buildings needed for the educational programs of the Connecticut State Colleges, and
- WHEREAS, Among these is a science building at Southern Connecticut State College, a campus at which laboratory facilities are totally inadequate resulting in a situation in which every year hundreds of the students enrolled in science courses get little or no laboratory instruction, and
- WHEREAS, Also among these is a student residence at Western Connecticut State College, a campus which is able to provide housing for only one out of every five students who apply to live in a college residence, and
- WHEREAS, The Trustees understand that these vital projects have been tied up for months in the Properties Review Board; therefore, be it
- RESOLVED, That the Trustees express their gratitude to the Governor, the General Assembly, the Board of Higher Education, and the Commissioner of Public Works for their support of these projects which are urgently needed to provide for the needs of students, and be it
- RESOLVED, That the Trustees hereby urge the Properties Review Board to end the prolonged delay and to take immediate steps to bring these projects to fruition, and be it
- RESOLVED, That the Governor, Members of the General Assembly, the Board of Higher Education, and the Commissioner of Public Works be, and hereby are, requested to inform the Properties Review Board of their understanding of the needs of students, their support for these projects, and that they, in turn, urge the Properties Review Board to take immediate steps to bring these projects to completion.

A Certified True Copy:

  
James A. Frost  
Executive Director

In our opinion

# Lost again between cracks

It has been obvious for a long time that a president or a governor proposes but the Congress or a legislature disposes.

Now we have a new twist in Connecticut. The governor and the General Assembly propose but a stubborn commissioner or a recalcitrant bureaucrat disposes (or blocks matters from being disposed of in an orderly fashion).

That seems to be the story of the handling of the architectural contract for the new dormitory on the westside campus of Western Connecticut State College, which Governor Ella Grasso proposed in October, 1976, and for which funding became available, thanks to legislative as well as gubernatorial action, on July 1, 1977.

Not only has the dormitory project been delayed, but apparently the same fate has befallen a score of other design or engineering contracts which became caught up in bureaucratic wrangling involving the public works division, the properties review board and the Department of Administrative Services.

The latter is supposed to be a key department in the reorganization of state government, which takes full effect Jan. 1. Its first commissioner, Daniel MacKinnon, was fired by Governor Grasso several weeks ago. She blamed him for disrupting

the new department and criticized his attitude toward other state employees.

MacKinnon replied with a letter to Governor McCollam Jr., Governor Grasso's administrative aide, and at the governor's request McCollam was promoting political harmony when he urged selection of an architect for the dormitory project. MacKinnon has also been a candidate for the Republican nomination for Congress in the Sixth District.

The firm picked for the contract has no credentials, as far as its work in this part of the state is concerned. It has signed its part of the contract and it's hard to understand why the other end is still tied up in the properties review board.

The latter was set up in answer to a long list of construction scandals which occurred in considerable number during the Grasso administration. It's intended as a review agency, not as another bottleneck in the orderly accomplishment of proposals which the governor has sponsored and which legislators have approved, or which legislators have sponsored and which the governor has approved.

The immediate task is to get the dormitory project and other delayed projects cleared for action. The next task will be either administrative or legislative or both to make sure that such delays don't occur again.

Self-Liquidating Facilities - Amortization Projections  
as of May 11, 1978

|                | \$4,348,000<br>(A)<br>6/30/77 | \$4,000,000<br>(A)<br>7/1/78 | \$3,000,000<br>(A)<br>7/1/79 | \$3,000,000<br>(A)<br>7/1/80 | Total<br>Expenditures | Balance    | Total*<br>Revenue | (B)<br>Fees | (C)<br>(6%)<br>Interest |
|----------------|-------------------------------|------------------------------|------------------------------|------------------------------|-----------------------|------------|-------------------|-------------|-------------------------|
| Balance 7/1/77 |                               |                              |                              |                              |                       | 7,565,144  |                   |             |                         |
| 77-78          | 3,332,123.75                  |                              |                              |                              | 3,332,123.75          | 6,196,929  | 1,963,909         | 1,510,000   | 453,909                 |
| 78-79          | 3,237,932.50                  | 478,280                      |                              |                              | 3,716,212.50          | 5,862,532  | 3,381,816         | 3,010,000   | 371,816                 |
| 79-80          | 2,926,470                     | 465,236                      | 440,000                      |                              | 3,831,706             | 5,392,578  | 3,361,752         | 3,010,000   | 351,752                 |
| 80-81          | 2,839,145                     | 452,192                      | 428,000                      | 330,000                      | 4,049,337             | 4,676,796  | 3,333,555         | 3,010,000   | 323,555                 |
| 81-82          | 2,746,277.50                  | 439,148                      | 416,000                      | 321,000                      | 3,922,425.50          | 4,044,978  | 3,290,608         | 3,010,000   | 280,608                 |
| 82-83          | 2,658,492.50                  | 426,104                      | 404,000                      | 312,000                      | 3,800,596.50          | 3,497,080  | 3,252,699         | 3,010,000   | 242,699                 |
| 83-84          | 2,570,676                     | 413,060                      | 392,000                      | 303,000                      | 3,678,736             | 3,038,169  | 3,219,825         | 3,010,000   | 209,825                 |
| 84-85          | 2,482,578.50                  | 400,016                      | 380,000                      | 294,000                      | 3,556,594.50          | 2,673,864  | 3,192,290         | 3,010,000   | 182,290                 |
| 85-86          | 2,148,232.50                  | 386,972                      | 368,000                      | 285,000                      | 3,188,204.50          | 2,656,091  | 3,170,432         | 3,010,000   | 160,432                 |
| 86-87          | 1,939,437.50                  | 373,928                      | 356,000                      | 276,000                      | 2,945,365.50          | 2,880,090  | 3,169,365         | 3,010,000   | 159,365                 |
| 87-88          | 1,362,275                     | 360,884                      | 344,000                      | 267,000                      | 2,334,159             | 3,728,736  | 3,182,805         | 3,010,000   | 172,805                 |
| 88-89          | 1,303,362.50                  | 347,840                      | 332,000                      | 258,000                      | 2,241,202.50          | 4,721,257  | 3,233,724         | 3,010,000   | 223,724                 |
| 89-90          | 1,239,450                     | 334,796                      | 320,000                      | 249,000                      | 2,143,246             | 5,871,286  | 3,293,275         | 3,010,000   | 283,275                 |
| 90-91          | 694,925                       | 321,752                      | 308,000                      | 240,000                      | 1,564,677             | 7,668,886  | 3,362,277         | 3,010,000   | 352,277                 |
| 91-92          | 514,775                       | 308,708                      | 296,000                      | 231,000                      | 1,350,483             | 9,788,536  | 3,470,133         | 3,010,000   | 460,133                 |
| 92-93          | 262,500                       | 295,664                      | 284,000                      | 222,000                      | 1,064,164             | 12,321,684 | 3,597,312         | 3,010,000   | 587,312                 |
| 93-94          |                               | 282,620                      | 272,000                      | 213,000                      | 767,620               | 15,303,365 | 3,749,301         | 3,010,000   | 739,301                 |
| 94-95          |                               | 269,576                      | 260,000                      | 204,000                      | 733,576               | 18,497,991 | 3,928,202         | 3,010,000   | 918,202                 |
| 95-96          |                               | 256,532                      | 248,000                      | 195,000                      | 699,532               | 21,918,338 | 4,119,879         | 3,010,000   | 1,109,879               |
| 96-97          |                               | 243,488                      | 236,000                      | 186,000                      | 665,488               | 25,577,950 | 4,325,100         | 3,010,000   | 1,315,100               |
| 97-98          |                               | 230,444                      | 224,000                      | 177,000                      | 631,444               | 29,491,183 | 4,544,677         | 3,010,000   | 1,534,677               |
| 98-2000        |                               |                              | 212,000                      | 168,000                      | 380,000               | 33,890,654 | 4,799,471         | 3,010,000   | 1,769,471               |
| 2000/2001      |                               |                              |                              | 159,000                      | 159,000               | 38,775,093 | 5,043,439         | 3,010,000   | 2,033,439               |

(A) Arbitrary distribution of bonding of \$11,348,000 available for student housing at Eastern, Southern & Western at 6% interest rate per annum. Probably premature by one year.

(C) 6% rate is slightly under 6.25% suggested by Office of the State Treasurer but is applied to full prior year balance which is not fully invested, there being some cash available at all times.

(B) Fees based on:

|                        |           |                  |
|------------------------|-----------|------------------|
| 18,000 In-State        | @ \$150 = | 2,700,000        |
| 1,000 Out-of-State     | @ 500 =   | 500,000          |
| 5,000 Application Fees | @ 10 =    | 50,000           |
| Total                  |           | <u>3,250,000</u> |

Less, \$20,000 monthly transfer to Auxiliary Services Fund (Major repair, renovation reserve)

Net annual fees 240,000  
3,010,000

\* For 1977-78 revenue has been reduced by \$1,500,000 through diversion to meet the costs of elimination of fire and other safety hazards.

# Interdepartment Message

STG-201 REV. 3/74 STATE OF CONNECTICUT  
(Stock No. 6938-051-01)

SAVE TIME: *Handwritten messages are acceptable.*

*Use carbon if you really need a copy. If typewritten, ignore faint lines.*

|             |        |                    |         |                    |           |              |
|-------------|--------|--------------------|---------|--------------------|-----------|--------------|
| <b>To</b>   | NAME   | Dr. James A. Frost | TITLE   | Executive Director | DATE      | May 30, 1978 |
|             | AGENCY |                    | ADDRESS |                    |           |              |
| <b>From</b> | NAME   | Brendan J. Kennedy | TITLE   |                    | TELEPHONE |              |
|             | AGENCY |                    | ADDRESS |                    |           |              |

SUBJECT: Request for fire and safety repairs in Auxiliary Service Buildings

EASTERN CONNECTICUT STATE COLLEGE

- Grandall Hall  
- Amortization Projections  
11, 1978

| Do | Total Expenditures | Balance    | Total* Revenue | (B) Fees  | (C) (6%) Interest |
|----|--------------------|------------|----------------|-----------|-------------------|
|    |                    | 7,565,144  |                |           |                   |
|    | 3,332,123.75       | 6,196,929  | 1,963,909      | 1,510,000 | 453,909           |
|    | 3,716,212.50       | 5,862,532  | 3,381,816      | 3,010,000 | 371,816           |
|    | 3,831,706          | 5,392,578  | 3,361,752      | 3,010,000 | 351,752           |
|    | 4,049,337          | 4,676,796  | 3,333,555      | 3,010,000 | 323,555           |
|    | 3,922,425.50       | 4,044,978  | 3,290,608      | 3,010,000 | 280,608           |
|    | 3,800,596.50       | 3,497,080  | 3,252,699      | 3,010,000 | 242,699           |
|    | 3,678,736          | 3,038,169  | 3,219,825      | 3,010,000 | 209,825           |
|    | 3,556,594.50       | 2,673,864  | 3,192,290      | 3,010,000 | 182,290           |
|    | 3,188,204.50       | 2,656,091  | 3,170,432      | 3,010,000 | 160,432           |
|    | 2,945,365.50       | 2,880,090  | 3,169,365      | 3,010,000 | 159,365           |
|    | 2,334,159          | 3,728,736  | 3,182,805      | 3,010,000 | 172,805           |
|    | 2,241,202.50       | 4,721,257  | 3,233,724      | 3,010,000 | 223,724           |
|    | 2,143,246          | 5,871,286  | 3,293,275      | 3,010,000 | 283,275           |
|    | 1,564,677          | 7,668,886  | 3,362,277      | 3,010,000 | 352,277           |
|    | 1,350,483          | 9,788,536  | 3,470,133      | 3,010,000 | 460,133           |
|    | 1,064,164          | 12,321,684 | 3,597,312      | 3,010,000 | 587,312           |
|    | 767,620            | 15,303,365 | 3,749,301      | 3,010,000 | 739,301           |
|    | 733,576            | 18,497,991 | 3,928,202      | 3,010,000 | 918,202           |
|    | 699,532            | 21,918,338 | 4,119,879      | 3,010,000 | 1,109,879         |
|    | 665,488            | 25,577,950 | 4,325,100      | 3,010,000 | 1,315,100         |
|    | 631,444            | 29,491,183 | 4,544,677      | 3,010,000 | 1,534,677         |
|    | 380,000            | 33,890,654 | 4,799,471      | 3,010,000 | 1,769,471         |
|    | 159,000            | 38,775,093 | 5,043,439      | 3,010,000 | 2,033,439         |

(C) 6% rate is slightly under 6.25% suggested by Office of the State Treasurer but is applied to full prior year balance which is not fully invested, there being some cash available at all times.

\$  
00,000  
00,000  
50,000  
50,000

## Con't ECSC

WINTHROP HALL

|                           |  |             |
|---------------------------|--|-------------|
| Flammable liquids locker  |  | \$ 5,000.00 |
| Ceiling Tiles             |  | 45,000.00   |
| North Stairway, 2nd floor |  | 3,000.00    |

|  |               |  |
|--|---------------|--|
| Fire Doors (20) - wood                       | \$1,500.00    |  |
| Door Closers (20)                            | 600.00        |  |
| Panic Hardware (8)                           | 1,200.00      |  |
| Locksets (2)                                 | 150.00        |  |
| Door Jambs (4) - "B" Label, single,<br>steel | <u>400.00</u> |  |

|                           |            |
|---------------------------|------------|
| Approx. Cost of Materials | \$3,850.00 |
| Approx. Cost of Labor     | 3,800.00   |

|  |          |
|--|----------|
| Approx. Total Cost of Material & Labor | 7,650.00 |
|--|----------|

Replace Existing Fire Alarm System and  
upgrade same, including smoke & heat  
detectors -

|                                   |           |
|-----------------------------------|-----------|
| Approx. Cost of Materials & Labor | 24,031.00 |
|-----------------------------------|-----------|

Replace Batteries in Existing Emergency  
Lighting System and upgrade same,  
including additional Exit & Emergency  
Light Units -

|                                   |                 |
|-----------------------------------|-----------------|
| Approx. Cost of Materials & Labor | <u>8,450.00</u> |
|-----------------------------------|-----------------|

APPROX. TOTAL COST TO UPGRADE WINTHROP HALL

\$93,131.00

HIGH RISE APARTMENTS

|                     |  |          |
|---------------------|--|----------|
| Pump Room Partition |  | 1,000.00 |
|---------------------|--|----------|

|   |                 |  |
|---|-----------------|--|
| Fire Doors (55) - steel                         | \$11,000.00     |  |
| Door Closers (57)                               | 1,710.00        |  |
| Panic Hardware (37)                             | 5,550.00        |  |
| Locksets (19)                                   | 1,425.00        |  |
| Hinges (103 pr.)                                | 5,000.00        |  |
| Mullions (18)                                   | 1,080.00        |  |
| Door Jamb (1) - "B" Label, single,<br>steel -   | 100.00          |  |
| Door Frame (18) - "B" Label, double,<br>steel - | <u>2,700.00</u> |  |

|                           |             |
|---------------------------|-------------|
| Approx. Cost of Materials | \$28,565.00 |
| Approx. Cost of Labor     | 28,800.00   |

|   |           |
|---|-----------|
| Approx. Total Cost of Materials & Labor | 57,365.00 |
|---|-----------|

Con't

## Con't ECSC - High Rise Apartments

Replace Existing Fire Alarm System and Upgrade  
same, including Smoke & Heat Detectors and  
connect same into City Fire Alarm

47,875.00

APPROX. TOTAL COST TO UPGRADE HIGH RISE APARTMENTS

\$106,240.00

NATHAN HALE HALL

|                                |            |
|--------------------------------|------------|
| Flammable Liquid Locker        | 1,000.00   |
| Fire Exit Stairtower           | 500,000.00 |
| Renovate Elevator              | 50,000.00  |
| Furnace Room Vents             | 1,000.00   |
| Exit from Basement             | 10,000.00  |
| Replace Combustible Partitions | 5,000.00   |
| Ballroom Exit                  | 5,000.00   |
| Fire Dampers                   | 5,000.00   |
| Clothes Dryer Vent             | 2,000.00   |

|  |               |
|--|---------------|
| Fire Doors (105) - wood                        | \$7,875.00    |
| Door Closers (42)                              | 1,260.00      |
| Panic Hardware (11)                            | 1,650.00      |
| Locksets (28)                                  | 1,935.00      |
| Hinges (75 pr.)                                | 7,550.00      |
| Door Jambs (8) - "B" Label,<br>single, steel - | <u>800.00</u> |

|                                 |                  |
|---------------------------------|------------------|
| Approx. Total Cost of Materials | \$21,070.00      |
| Approx. Total Cost of Labor     | <u>21,600.00</u> |

|   |           |
|---|-----------|
| Approx. Total Cost of Materials & Labor | 42,670.00 |
|---|-----------|

|   |                 |
|---|-----------------|
| Install Additional Smoke & Heat Detectors | <u>5,450.00</u> |
|---|-----------------|

APPROX. TOTAL COST TO UPGRADE NATHAN HALE HALL

\$627,120.00

BURR HALL

|                         |            |
|-------------------------|------------|
| Fireplace Brickwork     | \$1,000.00 |
| Ceiling Tiles           | 35,000.00  |
| Seal Air Shafts         | 5,000.00   |
| Relocate Washer & Dryer | 1,000.00   |
| Vent Gas Meter Room     | 1,000.00   |
| Flammable Liquid Locker | 1,000.00   |
| Vent Generator Room     | 1,000.00   |

Con't

## Con't ECSC - Burr Hall

|  |                  |                  |
|--|------------------|------------------|
| Fire Doors (58) - wood   | \$4,350.00       |                  |
| Door Closers (45)  | 1,350.00         |                  |
| Panic Hardware (20)  | 3,000.00         |                  |
| Locksets (35)  | 2,625.00         |                  |
| Hinges (98 pr.)  | 3,250.00         |                  |
| Fire Doors (4) - steel   | 800.00           |                  |
| Door Frames (4) - steel  | 200.00           |                  |
| Door Jambs (12) - "B" Label,<br>single, steel -  | 1,200.00         |                  |
| Door Jambs (4) - "B" Label,<br>double, steel -   | <u>600.00</u>    |                  |
| Approx. Total Cost of Materials  | \$17,375.00      |                  |
| Approx. Total Cost of Labor  | <u>18,200.00</u> |                  |
| Approx. Total Cost of Materials & Labor  |                  | 35,575.00        |
| To close in Transoms -   |                  |                  |
| Approx. Cost of Materials  | 2,800.00         |                  |
| Approx. Cost of Labor  | <u>2,800.00</u>  |                  |
| Approx. Total Cost of Materials & Labor  |                  | 5,600.00         |
| Replace Existing Fire Alarm System and<br>upgrade same, including Smoke & Heat Detectors -                 |                  |                  |
| Approx. Cost of Materials & Labor  |                  | 26,560.00        |
| Replace Existing Gas Generator Emergency System<br>to Central Battery Emergency System & upgrade<br>same - |                  |                  |
| Approx. Cost of Materials & Labor  |                  | <u>16,815.00</u> |
| APPROX. TOTAL COST TO UPGRADE BURR HALL  |                  | \$129,550.00     |

LOW RISE APARTMENTS

Install a new complete Fire Alarm System for each complex, including Smoke & Heat Detectors, and connect same into City Fire Alarm System -

APPROX. COST OF MATERIALS & LABOR

\$ 46,500.00

TOTAL REPAIRS FOR EASTERN

\$1,034,001.00

WESTERN CONNECTICUT STATE COLLEGEStudent Center

|   |                 |                  |
|---|-----------------|------------------|
| Replace Doors                                       | \$ 1,656.00     |                  |
| Door closers  | 2,070.00        |                  |
| Exit Signs  | 311.00          |                  |
| Misc. Carpentry                                     | 2,484.00        |                  |
| Fireproofing Int. Walls<br>and Doors                | 6,789.00        |                  |
| Additional Exits                                    | <u>4,975.00</u> |                  |
| Total Cost  |                 | \$18,285.00      |
| Upgrade Fire Alarm System and<br>Emergency Lighting |                 | <u>45,000.00</u> |
| APPROX. TOTAL COST TO UPGRADE STUDENT CENTER        |                 | \$ 63,285.00     |

Fairfield Hall

|   |                 |                  |
|---|-----------------|------------------|
| Replace Doors                                       | \$36,225.00     |                  |
| Door closers  | 3,105.00        |                  |
| Exit Signs  | 1,035.00        |                  |
| Misc. Carpentry                                     | <u>2,898.00</u> |                  |
| Total Cost  |                 | \$43,263.00      |
| Upgrade Fire Alarm System and<br>Emergency Lighting |                 | <u>60,000.00</u> |
| APPROX. TOTAL COST TO UPGRADE FAIRFIELD HALL        |                 | \$103,263.00     |

Litchfield Hall

|   |                 |                  |
|---|-----------------|------------------|
| Replace Doors                                       | \$ 9,212.00     |                  |
| Door closers  | 1,035.00        |                  |
| Exit Signs  | 1,035.00        |                  |
| Misc. Carpentry                                     | 3,105.00        |                  |
| Hvac Vent Baths                                     | <u>8,280.00</u> |                  |
| Total Cost  |                 | \$22,667.00      |
| Upgrade Fire Alarm System and<br>Emergency Lighting |                 | <u>30,000.00</u> |
| APPROX. TOTAL COST TO UPGRADE LITCHFIELD HALL       |                 | \$ 52,667.00     |

Con't



Con't WCSC

Newbury Hall

|                 |                 |             |
|-----------------|-----------------|-------------|
| Replace Doors   | \$ 2,484.00     |             |
| Door closers    | 1,656.00        |             |
| Exit Signs      | 414.00          |             |
| Misc. Carpentry | 931.00          |             |
| Hvac Vent Baths | <u>8,280.00</u> |             |
| Total Cost      |                 | \$13,765.00 |

|   |  |                  |
|---|--|------------------|
| Upgrade Fire Alarm System and<br>Emergency Lighting |  | <u>30,000.00</u> |
|---|--|------------------|

|  |  |              |
|--|--|--------------|
| APPROX. TOTAL COST TO UPGRADE NEWBURY HALL |  | \$ 43,765.00 |
|--|--|--------------|

|                        |  |                     |
|------------------------|--|---------------------|
| System Wide Fire Alarm |  | <u>\$ 36,000.00</u> |
|------------------------|--|---------------------|

|                           |  |                     |
|---------------------------|--|---------------------|
| TOTAL REPAIRS FOR WESTERN |  | <u>\$298,980.00</u> |
|---------------------------|--|---------------------|

SOUTHERN CONNECTICUT STATE COLLEGEStudent Center

|  |  |           |
|--|--|-----------|
| Self-closing device on doors to<br>alumni room |  | \$ 676.00 |
|--|--|-----------|

Hickerson Hall

|  |  |             |
|--|--|-------------|
| Latches on all stairtower exit doors<br>Proper rated door to pump room |  |             |
| Total Cost   |  | \$ 3,284.00 |

Wilkinson Hall

|   |  |             |
|---|--|-------------|
| Self closing device on storage room door<br>(east wing)   |  |             |
| Self closing device on basement kitchen door  |  |             |
| Replace unrated louvered door to basement fan room<br>with proper "B" label, 1½ hour rated door |  |             |
| Self closing device on first floor kitchen door   |  |             |
| Total Cost  |  | \$ 4,698.00 |

con't

May 30, 1978

## Con't SCSC

Farnham Hall

Self closing device on kitchen door  
 (first floor main corridor)  
 door to kitchen in basement recreation area

Total Cost \$ 4,060.00

Chase Hall

Replace louver door to mechanical room with  
 proper rated door  
 Self closing device on kitchen door  
 (first floor)  
 Self closing device on kitchen doors  
 (Room #14)

Total Cost \$ 4,452.00

Neff Hall

Enclose storage rooms located on each floor of  
 student sleeping areas with fire resistant  
 materials.

Provide a "B" labeled fire rated door at each  
 opening.

Positive latches on all stairtower exit doors

Self-closing device on kitchen door  
 (1st floor)

Self-closing device on basement kitchen door

Replace all broken and missing ceiling tile in base-  
 ment recreation room.

Total Cost \$19,034.00

Schwartz Hall

Exit doors into stairtowers be provided with  
 positive hold latches.

Remove dead bolt locks on exit doors in  
 recreation room and replace with school-  
 house type or other approved locks.

Total Cost \$ 5,096.00

TOTAL REPAIRS FOR SOUTHERN

\$ 41,300.00

TOTAL REPAIRS FOR EASTERN, WESTERN & SOUTHERN

\$1,374,281.00